Scope of	Work for Property Loc	cated	at:		5	5300 North 46th Street	
	Property is: Single Far	nily	y	Duplex	(□ Other □	
Date:	12/14/2015						
take no respo	onsibility for problems discovered	after the	e ins	pection da	ite,	The City of Milwaukee, the Redevelopment A or for omissions through error or oversight. Il Block Grant or HOME programs.	
Exterior	Condition Report						
Location Site	Required Work Landscaping	n/a	7	Yes □		lote/Comments elf Help	\$ Cost
	Steps/Handrails	n/a	7	Yes □			\$
	Service walks	n/a	4	Yes □			\$
	Fencing	n/a	7	Yes □			\$
	Parking	n/a		Yes ☑	li	nstall parking slab	\$ 3,000.00
	Retaining walls	n/a	1	Yes □			\$
	Other	n/a		Yes □			\$
	Other	n/a		Yes □			\$
Garage	Singles: repair	n/a		Yes □			\$
	Shingles: Roof over existing	n/a		Yes □			\$
	Shingles:Tear off & re-roof	n/a		Yes □			\$
	Gutters/downspouts	n/a		Yes □			\$
	Flashing	n/a		Yes □			\$
	Eaves	n/a		Yes □			\$
	Siding	n/a		Yes □			\$
	Doors	n/a		Yes □			\$
	Windows	n/a		Yes □			\$
	Slab	n/a		Yes □			\$
	Paint	n/a		Yes □			\$
	Electrical	n/a		Yes □			\$
	Other	n/a		Yes □			\$
Porches	Roof	n/a	V	Yes □			\$
	Deck-upper	n/a	7	Yes □			\$
	Decklower	n/a	7	Yes □			\$
	Steps/handrails	n/a		Yes 🗹	F	Remove side entry guardrail	\$ 75.00
	Ceiling	n/a	7	Yes 🗆			\$
	Guardrails	n/a	7	Yes 🗆			\$
	Structural	n/a	7	Yes □			\$
	Paint	n/a	7	Yes 🗆			\$

n/a ☐ Yes ☑ Front Stoop

Other

\$

500.00

House

Chimney	n/a ☑	Yes □		\$
Shingles: repair	n/a ☑	Yes 🗆		\$
Shingles: Roof over existing	n/a ☑	Yes □		\$
Shingles:Tear off & re-roof	n/a □	Yes 🗸		\$ 7,000.00
Gutters/downspouts	n/a □	Yes 🗹		\$ 750.00
Flashing	n/a ☑	Yes □		\$
Eaves	n/a ☑	Yes □		\$
Siding	n/a _□	Yes ☑	Repairs	\$ 300.00
Storm Doors	n/a □	Yes ☑		\$ 300.00
Prime ("main") Doors	n/a □	Yes ☑		\$ 500.00
Storm Windows	n/a ☑	Yes □		\$
Prime ("main") Windows	n/a □	Yes ☑		\$ 1,000.00
Paint	n/a □	Yes ☑		\$ 1,200.00
Foundation	n/a □	Yes ☑	Basement walls bowed	\$ 25,000.00
Electrical	n/a _☑	Yes 🗆		\$
Other	n/a □	Yes ☑	Address labels on back of dwelling	\$ 50.00
Other	n/a □	Yes 🗆		\$
Other	n/a □	Yes 🗆		\$
Other	n/a □	Yes 🗆		\$

Exterior: Estimated Cost:* \$ 39,675.00
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report				
	Unit: Entire unit (single family) Upper unit of duplex	✓		Lower unit of duplex ☐ Other ☐	
Mechanical Heating	Required Work				
ricating	Repair/replace boiler	n/a ☑	Yes □		\$
	Repair radiation	n/a ☑	Yes □		\$
	Repair/replace furnace	n/a □	Yes ☑	Remove inoperable upper space heater	\$ 150.00
	Repair ductwork	n/a ☑	Yes □		\$
	Replace thermostat	n/a ☑	Yes □		\$
	Repair/replace grilles	n/a ☑	Yes 🗆		\$
Floatwinel	Tune boiler/furn. insp ht exchang	€n/a □	Yes ☑		\$ 350.00
Electrical	Repair/replace receptacles	n/a □	Yes 🗸	-	\$
	Repair/replace switches	n/a ☑	Yes 🗆		\$
	Repair/replace fixtures	n/a □	Yes ☑	=	\$ 200.00
	Install outlets and circuits	n/a ☑	Yes 🗆		\$
	Install outlets and circuits	n/a ☑	Yes □		\$
	Install outlets and circuits	n/a ☑	Yes □		\$
	Install outlets and circuits	n/a 🗹	Yes □		\$
	Upgrade service	n/a _□	Yes ☑	_	\$ 2,000.00
	Other	n/a □	Yes ☑	Range hood	\$ 150.00
Diversións	Other	n/a 🔲	Yes 🗹	open junction boxes & missing outlet covers	\$ 100.00
Plumbing	Repair/replace kitchen sink	n/a ☑	Yes 🗆		\$
	Repair/replace kitchen sink fauce	n/a 🔲	Yes ☑		\$ 300.00
	Repair/replace tub	n/a ☑	Yes 🗆	_	\$
	Repair/replace tub faucet	n/a ☑	Yes □		\$
	Repair/replace toilet	n/a 🗹	Yes 🗆		\$
	Repair/replace lavatory	n/a ☑	Yes □	_	\$
	Repair/replace lavatory faucet	n/a ☑	Yes □	-	\$
	Repair/replace wash tub	n/a □	Yes ☑		\$ 750.00
	Repair/replace wash tub faucet	n/a 🗹	Yes □		\$
	Unclog piping:	n/a ☑	Yes □		\$
	Repair drain/waste/vent piping	n/a □	Yes 🗹		\$ 600.00
	Repair water piping	n/a □	Yes 🗸		\$ 300.00
	Repair/replace water heater	n/a ☑	Yes □	_	\$
	Other	n/a □	Yes ☑	Kitchen dishwasher	\$ 300.00
	Other	n/a □	Yes ☑	Tub surround	\$ 500.00

Windows						
	Replace broken glass	n/a <u></u> ✓	Yes			\$
	Repair or replace sash	n/a ☑	Yes			\$
Doors	Repair or replace doors	n/a □	Yes	7		\$ 200.00
	Repair or repl. locks/latches	n/a □	Yes	V	Self Help	\$ 120.00
Walls/Ceiling	gs Repair or repl. @ defective	n/a □	Yes	7		\$ 300.00
Paint	Repair or repl. @ defective	n/a □	Yes	7		\$ 900.00
Fire Safety						
_	Install smoke/CO alarm:bsmt.	n/a □	Yes	V	Self Help	\$ 60.00
	Install smoke/CO alarm: 1st flr.	n/a □	Yes	7	Self Help	\$ 60.00
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes	7	Self Help	\$ 60.00
Handrails	Repair/replace defective	n/a ☑	Yes		Self Help	\$
Stairs	Repair defective	n/a □	Yes	7		\$ 300.00
Floors	December defending	/	V			1 000 00
Other	Repair defective	n/a □	Yes	7		\$ 1,200.00
		n/a □	Yes	V	Secure kitchen cabinets to wall	\$ 100.00
		n/a □	Yes	7	General interior cleaning	\$ 500.00
		n/a □	Yes			\$
		n/a 🗆	Yes		9	\$
					Interior: Estimated Cost:	\$ 9,500.00
					Total Exterior and Interior Cost:*	\$ 49,175.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Inspected by: Mark Stack Date: 12/14/2015

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.